Best Available Copy



AD-A167 420

Photodesorption Cleaning of Silicon with Vacuum Ultraviolet Irradiation

Prepared by

A. R. CALLOWAY and P. A. BERTRAND
Laboratory Operations
The Aerospace Corporation
El Segundo, CA 90245

4 April 1986

Sponsored by

DEFENSE ADVANCED RESEARCH PROJECTS AGENCY (DOD)
Monitored by Space Division under Contract No. F04701-83-C-0084

20030121080

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED



SPACE DIVISION
AIR FORCE SYSTEMS COMMAND
Los Angeles Air Force Station
P.O. Box 92960, Worldway Postal Center
Los Angeles, CA 90009-2960

REPRODUCTION QUALITY NOTICE

This document is the best quality available. The copy furnished to DTIC contained pages that may have the following quality problems:

- · Pages smaller or larger than normal.
- · Pages with background color or light colored printing.
- · Pages with small type or poor printing; and or
- Pages with continuous tone material or color photographs.

Due to various output media available these conditions may or may not cause poor legibility in the microfiche or hardcopy output you receive.

If this block is checked, the copy furnished to DTIC contained pages with color printing, that when reproduced in Black and White, may change detail of the original copy.

This document contains blank pages that were not filmed

This report was submitted by The Aerospace Corporation, El Segundo, CA 90245, under Contract No. F04701-83-C-0084 with the Space Division, P.O. Box 92960, Worldway Postal Center, Los Angeles, CA 90009. It was reviewed and approved for the Aerospace Corporation by G. A. Paulikas, Acting Director, Electronics Research Laboratory.

Lt Leonardo Fua, SD/CGXT, was the Air Force project officer.

This report has been reviewed by the Public Affairs Office (PAS) and is releasable to the National Technical Information Service (NTIS). At NTIS, it will be available to the general public, including foreign nationals.

This technical report has been reviewed and is approved for publication. Publication of this report does not constitute Air Force approval of the report's findings or conclusions. It is published only for the exchange and stimulation of ideas.

LEONARDO FUA, Lt, USAF

MOIE Project Officer

SD/CGXT

JOSEPH HESS, GM-15

Director, AFSTC West Coast Office

AFSTC/WCO OL-AB


Unclassified
SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION F	i i	BEFORE COMPLETING FORM		
SD-TR-86-18	2. GOVT ACCESSION NO.	2 O		
4. TITLE (and Subtitle)		S. TYPE OF REPORT & PERIOD COVERED		
 PHOTODESORPTION CLEANING OF SILICON	1			
WITH VACUUM ULTRAVIOLET IRRADIATION		6. Performing ord, report humber TR-0086(6766)-1		
7. AUTHOR(s)		8. CONTRACT OR GRANT NUMBER(s)		
A. R. Calloway and P. A. Bertrand		F04701-85-C-0086		
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS		
The Aerospace Corporation Fl Segundo, CA 90245				
11. CONTROLLING OFFICE NAME AND ADDRESS Defense Advanced Research Projects	Agency	12. REPORT DATE 4 April 1986		
1400 Wilson Blvd. Arlington, VA 22209		13. NUMBER OF PAGES 17		
14. HONITORING AGENCY NAME & ADDRESS(If dillorent	trem Centrelling Office)	15. SECURITY CLASS. (of this report)		
Space Division		Unclassified		
Los Angeles Air Force Station Los Angeles, CA 90009-2960	·	15a, DECLASSIFICATION/DOWNGRADING		
16. DISTRIBUTION STATEMENT (of this Report)				
Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the obstreet entered in Block 20, if different from Report)				
18. SUPPLEMENTARY NOTES				
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Vacuum—ultraviolet irradiation Argon lamp Carbonyl adsorbates Xenon lamp Hydrocarbon adsorbates Aliphatic hydrocarbons Auger spectrometer				
20. ABSTRACT (Continue on reverse side if necessary and	identify by block number)			
An investigation into the use of vacuum-ultraviolet irradiation for photodesorption cleaning of the surface of silicon contaminated by carbonyl and hydrocarbon adsorbates has been made.				
Rogeret malety-				

DD FORM 1473

PREFACE

The support of DARPA under contract No. F04701-85-C-0086 for this work is gratefully acknowledged. The authors also thank Mr. Jeffery Childs for his assistance in obtaining the XPS spectra.





CONTENTS

PRE	CE	1
ı.	NTRODUCTION	7
2.	EXPERIMENT PROCEDURE	9
3.	ESULTS AND DISCUSSION	13
•	Photodesorption of Carbonyl Compounds	13
	Hydrocarbon Photodesorption	16
4.	CONCLUSIONS	19
र साम	ENCES	21

FIGURES

1.	Modified XPS System	10
2.	XP Spectrum of Si Surface	14
3.	XPS Spectrum of Si Surface	15
4.	Effect of Irradiation on Si-Si, So-O and HC and C=O Contaminants	17

1. INTRODUCTION

Carbon-containing compounds adsorb onto cleaned surfaces from ambient air and in some vacuum chambers [1,2,3,4]. Any operator of an x-ray photoelectron spectrometer (XPS), Auger spectrometer or secondary ion mass spectrometer (SIMS) can attest to the ubiquitousness of organic contaminants. Chang and coworkers [3] discovered that in spite of using exceptional care in the etching procedures for GaAs, carbon was present after etching and was not reduced appreciably by the thermal removal of the oxide layers. The effect of organic impurities between layers on semiconductor device performance is not fully known, however, it has been determined that contamination can cause poor adhesion of Cr/Au metallization to glass [1]. Chang, et al., have measured increased resistance and nonlinear I-V characteristics as a result of the presence of carbon between the GaAs substrate and an MBE grown n⁺-GaAs film [3]. Equally damaging to the vertical electron transport properties is the nonannealable (550°C) increased resistance that results from sputter-cleaning damage to the substrate surface prior to the growth of the n⁺-GaAs film.

The combination of ultraviolet irradiation and ozone has been determined to be effective for cleaning surfaces a measured by minimization of distilled water contact angles [1,5]. More sensitive surface analyses such as XPS and Auger spectroscopy have recently confirmed this method's effectiveness. However, it is recognized that the strong oxidizing properties of ozone may prove to be deleterious for some cleaning purposes [5].

できませんという。「個人となるとは、これには、これには、これには、一般のこれには、「個人となるとは、「個人となるとなって、」というという。「個人となるとは、「一般のこれには、「一般のこれには、「一般のこれには、「一般のこれには、「一般のこれには、「一般のこれを表現して、「一般のこれには、「一般のこれを表現して、「一般のこれを表現して、「一般のこれを表現して、「一般のこれを表現して、「一般のこれを表現して、「一般のこれを表現して、「一般のこれを表現して、「一般のこれを表現して、「一般のこれを表現して、

Recent studies have revealed a strong correlation between photon energy in the ultraviolet wavelength region and photodesorption effectiveness [6,7]. These studies did not include wavelengths shorter than 249 nm. However, the sharp increase in photodesorption signals with decreasing wavelength below 300 nm [7] suggests that wavelengths shorter than 240 nm may be even more effective in desorption processes.

A newly developed method of photochemical deposition uses the output of vacuum ultraviolet lamps to drive chemical vapor deposition (CVD) reactions [8,9]. A key step in the process (prior to the deposition) is the irradiation of the substrate surface with VUV light (105-190 nm) to volatilize spurious adsorbed material that is then removed by the vacuum system. Evidence of the effectiveness of this photodesorption cleaning step is the chemical bonding of VUV-CVD silicon to the surface of VUV pre-cleaned sapphire (Al $_2$ O $_3$) and quartz (SiO $_2$) [9]. This observation led us to investigate the photodesorption process in the vacuum ultraviolet region (λ < 190 nm) and to evaluate its effectiveness as a pre-cleaning step that may provide damage-free, superior interface properties between layers on semiconductor devices.

2. EXPERIMENT PROCEDURE

The (100) surface of n-type phosphorous doped silicon (Siltec Corp. lot #813732) was used for this study. A comparison of the XPS analysis before and after VUV exposure was made for the silicon as received versus those surfaces that had been chemically cleaned. The chemical cleaning was done in our laboratory and included the following steps: 1) 10 min. in warm 1:1 NH $_4$ OH/H $_2$ O $_2$, 10 min. rinse; 2) 10 min. in warm 1:2 HCl/H $_2$ O $_2$, 10 min. rinse; 3) 10 sec. in 10% HF, 10 min. rinse and spin dry. The cleaned silicon was then stored under nitrogen atmosphere at 600°C until used. The rinses in all cases were in 18 M Ω water. For simplicity, the samples that received this treatment will be referred to as clean samples.

A modified X-ray photoelectron spectrometer (GCA/McPherson ESCA 36) with a time-integrating, optical position-sensitive detection system (consisting of a channel electron multiplier array, a Princeton Applied Research model 1205 vidicon camera and an optical multichannel analyzer [10] was used for the surface analyses before and after VUV exposure. Modifications included the retrofitting of an Inficon model IQ 200 quadrupole mass spectrometer and our VUV lamps to the XPS chamber. The modified XPS system is illustrated in Figure 1. The sample stage, which could be moved from the X-ray source to the VUV source by an external manipulator arm, allowed XPS analysis before and after the VUV irradiation without exposure of the sample to the atmosphere.

Two types of in-house designed lamps were used in this study. In the initial phase, irradiation from the xenon continuum lamp was discovered to be effective in the photodesorption of a contaminant that contained a carbonyl structure (C=0). The xenon lamp's emission is in the wavelength region of 147 nm to 190 nm with a peak intensity at 160 nm '~ 8 eV/photon) [11]. An argon lamp was used to evaluate the shorter wavelength VUV photodesorption effectiveness. The emission spectrum of the argon lamp is believed to be similar to the one in reference 11 which has a peak intensity at 125 nm (~ 10 eV/photon). The argon lamp's design is similar to that of the xenon lamp except for the absence of a window on the VUV output end and the addition of a gas metering valve on the back end.




Figure 1. Modified XPS System

The chamber pressure was maintained at 2×10^{-7} torr by a turbomolecular pump and a helium cryo-pump during the XPS analysis and during the sample irradiation with the xenon lamp. The chamber pressure was maintained at 4 torr during the operation of the argon windowless lamp. Argon was flowed through the lamp at 200 cc/min into the XPS chamber and removed at the same rate through a metered valve by a turbomolecular pumping station. After the completion of an irradiation time period, the chamber was evacuated to 2×10^{-7} torr and XPS analysis performed.

Because of the high chamber pressure during the operation of the argon windowless lamp, there was no attempt to record the photodesorption products with the mass spectrometer.


3. RESULTS AND DISCUSSION


Analysis by XPS has revealed that the surface of silicon becomes contaminated with hydrocarbon (HC) and carbonyl (C=0) structured compounds in a normal laboratory atmosphere. The HC adsorbate levels were ~ 10 times the C=0 levels on all samples. Examples of additional compounds that are probably adsorbed but not always detectable by standard XPS analysis are H₂O, O₂ and N₂. Only the compounds detected by our XPS system will be discussed in this report. An XPS spectrum of the surface of cleaned silicon is shown in Figure 2. The peak at 285.0 eV is due to the C(ls) electron in aliphatic hydrocarbons. Figure 3 is an expanded view of this region which reveals a weak shifted band at 288.5 eV. This peak is from the C(ls) electron in a compound that contains a carbonyl structure (C=0). We evaluated the effect of vacuum ultraviolet irradiation on the photodesorption of the HC and C=0 adsorbates with respect to time and VUV wavelength.

3.1 PHOTODESORPTION OF CARBONYL COMPOUNDS

The 288.5 eV band was reduced to ~ 50% its original intensity after ten minutes of irradiation with the xenon continuum lamp (~ 8 eV/photon). After 20 minutes of exposure with the xenon lamp, the carbonyl contaminant was reduced to an undetwetable level. However, no measurable decrease in the hydrocarbon contamination was detectable after the xenon lamp exposure.

From the XPS analysis, we estimated that the carbonyl contaminant before exposure to VUV irradiation covers approximately 20% of the silicon surface. Assuming that each of the adsorbate molecules occupies a 10 2 area, then 2×10^{14} molecules would be adsorbed within a one cm² area. Since we measured a 50% decrease in the carbonyl compounds' signal after 10 minutes of irradiation, this would then correspond to $\approx 1 \times 10^{14}$ molecules removed in 600 seconds. Our xenon VUV lamp's output has been calibrated at 2×10^{15} photons/cm²sec. This means 1.2×10^{18} photons will impinge upon the silicon surface in 600 seconds. From these approximations and the measured lamp output, the 160 nm photodesorption efficiency of the carbonyl adsorbate can be approximated by





Pigure 3. Expanded XPS Spectrum of Si Surface

$$\frac{V_d}{V_d} = \frac{Nc}{Np} = 10^{-4}$$

where: Φ_d = photodesorption efficiency for carbonyl compounds

Nc = number of carbonyl molecules desorbed/sec

Np = number of incident photons/sec

The photodesorption efficiency value of 10^{-4} is a lower limit approximation due to the limited surface coverage by the carbonyl adsorbate compared to the total coverage by the VUV irradiation.

3.2 HYDROCARBON PHOTODESORPITION

There was no measurable reduction in the hydrocarbon (HC) XPS signal after irradiating the silicon surfaces with the output of the xenon lamp. This is believed due to insufficient overlap in the emission spectrum of the xenon lamp with the absorption of aliphatic hydrocarbons in the vacuum ultraviolet region [12]. This problem was overcome by using the windowless argon lamp, which emits at shorter wavelengths. Two minutes of irradiation with the windowless argon lamp reduced the HC on cleaned silicon to 20% of its original XPS intensity. It is interesting to note that during this same period the Si-Si and Si-O photoelectron signals at 99.8 and 103.5 eV both increased slightly (see Figure 4). Thus, VUV irradiation did not disrupt the Si-Si or Si-O bonding, nor did it remove Si from the surface. Assuming a smooth layer and an electron escape depth of ~ 20 Å, the hydrocarbon adsorbates are estimated to be 4 Å thick before irradiation. After irradiation, the layer is thinner, so electrons emitted from the underlying Si can escape the sample more easily, thus causing the observed increase in Si-Si and Si-O signal intensity. An additional seven minutes of irradiation reduced the HC XPS signal to 6% of the original intensity. The sample was then allowed to sit in the XPS chamber at 2×10^{-7} torr for two hours. This resulted in an increase in the HC adsorbates on the VUV-cleaned silicon surface. This increase is believed to be due to adsorption from a residual hydrocarbon vapor pressure in the XPS chamber. Increases in hydrocarbon levels on sample surfaces with time and X-ray exposure in XPS chambers have been observed by others [13]. X-ray exposure does not decrease the hydrocarbon and carbonyl




Figure 4. Effect of Irradiation on Si-Si, So-O and HC and C-O contaminants

levels even though there is heating of the sample. Nor does exposure of the silicon surface to the same pressure and flow of argon that was used during the VUV irradiation reduce these adsorbates. Only the ergon lamp was effective in photodesorbing both the hydrocarbon and carbonyl contaminants from the surface of silicon.

4. CONCLUSIONS

We have determined that the surface of silicon becomes contaminated with hydrocarbon and carbonyl adsorbates in a normal laboratory atmosphere and in a turbomolecular-pumped vacuum system. The adsorbates are strongly bound and are not removed by exposure to X-rays during XPS analysis. However, it was found that the carbonyl adsorbates are removed with 8 eV/photon irradiation and that both the carbonyl and hydrocarbon adsorbates are removed with 10 eV/photon irradiation.

The mass spectrometer was intended to identify the gaseous species as they were photodesorbed by VUV irradiation. For the conditions of this experiment, the volume of the XPS chamber and the pumping speed of the vacuum system were too great to permit this. Additional tests are planned that are expected to overcome these obstacles.

The 160 nm photodesorption efficiency value of 10^{-4} for carbonyl adsorbates from the surface of silicon is a lower limit approximation for the limited substrate coverages that were observed. It is large when compared to Genequand's value of 10^{-9} for the photodesorption efficiency of CO_2 from the surface of nickel with 253 nm irradiation [14]. Further testing will be required to determine if this large difference is due to more efficient desorption with shorter wavelength light or to photochemical decomposition of the contaminant by the shorter wavelength light.

As hydrocarbon compounds are excellent insulators (e.g., electrical wire insulation), their presence between layers on integrated circuits will tend to increase resistance and make the device less efficient. Additional work will be required to determine if the levels of contamination that we have found to spontaneously adsorb onto the surface of silicon will produce a deleterious effect.

REFERENCES

- R. R. Sowell, R. E. Cuthrell, C. M. Mattox, and R. D. Bland, "Surface Cleaning by Ultraviolet Radiation," <u>J. Vac. Sci. Technol.</u> 11, 474 (1974).
- E. S. Brandt, D. R. Untereker, C. N. Reilley and Royce W. Murray, "Comparison of Carbon Contaminant Buildup on Conductors and Insulators in X-ray Photoelectron Spectroscopy," J. Electron Spectrosco. Relat. Phenom. 14, 113 (1978).

第四個のではなるである。 1987年に対象のできることが、1987年に対象のできることが、1987年に対象のできることが、1987年に対象のできる。 1987年に対象のできることが、1987年に対象のできることが、1987年に対象のできる。

- 3. C. Chang, M. Heiblum, R. Ludeke, and M. I. Nathan, "Effect of Substrate Surface Treatment in Molecular Beam Epitaxy on the Vertical Electronic Transport Through the Film-Substrate Interface," Appl. Phys. Lett. 39, 229 (1981).
- 4. A. Y. Cho and M. B. Panish, "Magnesium-Doped GaAs and Al_xGa_{l-x}As by Molecular Beam Epitaxy," <u>J. Appl. Phys.</u> 43, 5118 (1972).
- 5. J. R. Vig, "UV Ozone Cleaning of Surfaces," 31st National Symposium of the American Vacuum Society, Reno, NV, 4-7 (December 1984).
- 6. V. S. Antonov, V. S. Letokhov, and A. N. Shibano, "Nonthermal Desorption of Molecular Ions of Polyatomic Molecules Induced by UV Laser Radiation," Appl. Phys. 25, 71 (1981).
- 7. N. V. Hieu and D. Lichtman, "Photodesorption Studies of CO₂ from an Oxygen-Saturated Silicon (100) Surface, <u>J. Vac. Sci. Technol. 1</u>, 1 (1983).
- 8. A. R. Calloway, T. A. Galantowicz, and W. R. Fenner, "Vacuum Ultraviolet-Driven Chemical Vapor Deposition of Localized Aluminum Thin Films, J. Vac. Sci., and Technol. Al 534 (1983).
- 9. A. R. Calloway and W. R. Fenner, "Vacuum-Ultraviolet-Driven Chemical Vapor Deposition of Semiconductors and Insulators," Aerospace Technical Report ATR-84(8503)-1, The Aerospace Corp., El Segundo, CA (May 1984).
- 10. P. A. Bertrand, W. J. Kalinowski, L. E. Tribble, and L. O. Tolentino, "Fast Optical Position-Sensitive Detector for McPherson ESCA-36," Sci. Instrum. 54(3), 387 (1983).
- 11. J. R. McNebsy, W. Braun, J. Ball, "Vacuum Ultraviolet Techniques in Photochemistry," from Creation and Detection of the Excited State, Vol. 1, Part B, ed. A. A. Lamola, Marcel Dekker, NY (1971).
- 12. E. E. Koch and M. Skibowski, "Optical Absorption of Gaseous Methane, Ethane, Propane and Butane and Reflection of Solid Methane and Ethane in the Vacuum Ultraviolet," <u>Chem. Phys. Lett.</u> 9, 429 (1971).

REFERENCES (Continued)

- N. S. McIntyre and M. G. Cook, "Some Quantitative Aspects of the X-Ray Photoelectron Spectroscopy Analysis of metal and Oxide Surfaces," from Surface Analysis Techniques for Metallurgical Applications, ed. R. S. Varbonara and J. R. Cuthill, ASTM Special Technical Publications No. 596 (1976).
- 14. P. Genequand, "Photodesorption," Surf. Sci. 25, 643 (1971).

LABORATORY OPERATIONS

The Aerospace Corporation functions as an "architect-engineer" for national security projects, specializing in advanced military space systems. Providing research support, the corporation's Laboratory Operations conducts experimental and theoretical investigations that focus on the application of scientific and technical advances to such systems. Vital to the success of these investigations is the technical staff's wide-ranging expertise and its ability to stay current with new developments. This expertise is enhanced by a research program simed at dealing with the many problems associated with rapidly evolving space systems. Contributing their capabilities to the research effort are these individual laboratories:

Aerophysics Laboratory: Launch vehicle and reentry fluid mechanics, heat transfer and flight dynamics; chemical and electric propulsion, propellant chemistry, chemical dynamics, environmental chemistry, trace detection; spacecraft structural mechanics, contamination, thermal and structural control; high temperature thermomechanics, gas kinetics and radiation; cw and pulsed chemical and excimer laser development including chemical kinetics, spectroscopy, optical resonators, beam control, atmospheric propagation, laser effects and countermeasures.

Chemistry and Physics Laboratory: Atmospheric chemical reactions, atmospheric optics, light scattering, state-specific chemical reactions and radiative signatures of missile plumes, sensor out-of-field-of-view rejection, applied laser spectroscopy, laser chemistry, laser optoelectronics, solar cell physics, battery electrochemistry, space vacuum and radiation effects on materials, lubrication and surface phenomena, thermionic emission, photosensitive materials and detectors, atomic frequency standards, and environmental chemistry.

Computer Science Laboratory: Program verification, program translation, performance-sensitive system design, distributed architectures for spaceborne computers, fault-tolerant computer systems, artificial intelligence, microelectronics applications, communication protocols, and computer security.

Electronics Research Laboratory: Microelectronics, solid-state device physics, compound semiconductors, radiation hardening; electro-optics, quantum electronics, solid-state lasers, optical propagation and communications; microwave semiconductor devices, microwave/millimeter wave measurements, diagnostics and radiometry, microwave/millimeter wave thermionic devices; atomic time and frequency standards; antennas, rf systems, electromagnetic propagation phenomena, space communication systems.

Materials Sciences Laboratory: Development of new materials: metals, alloys, ceramics, polymers and their composites, and new forms of carbon; non-destructive evaluation, component failure analysis and reliability; fracture mechanics and stress corrosion; analysis and evaluation of materials at cryogenic and elevated temperatures as well as in space and enemy-induced environments.

Space Sciences Laboratory: Magnetospheric, suroral and cosmic ray physics, wave-particle interactions, magnetospheric plasma waves; atmospheric and ionospheric physics, density and composition of the upper atmosphere, remote sensing using atmospheric radiation; solar physics, infrared astronomy, infrared signature analysis; effects of solar activity, magnetic atorms and nuclear explosions on the earth's atmosphere, ionosphere and magnetosphere; effects of electromagnetic and particulate radiations on space systems; space instrumentation.